



# Ethernet



## signal cable connector



## power supply cable



www.boundarydevices.com

TURNSTILE CONTROL  
UNIT  
( ARGON-TURNSTILE )

Title		
WIRING DIAGRAM FOR ARGON TURNSTILE		
Size	Document Number	Rev
A	<Doc>	
Date:	Tuesday, March 11, 2008	Sheet 1 of 1